


AIS WatchMate 670

CTRX Transponder Wiring Diagrams



Optional chart plotter/radar or external alarm

